




# Probing System SOP

How to Calibrate a Haas CNC.

Written By: Max Fishman



## INTRODUCTION

### Qualifications:

- Level 1 Safety Training
- CNC Operation Training

### PPE:

Please make sure you have the following PPE:

- Gloves
- Helmet
- Safety Glasses

### TOOLS:

- [Allen Wrench](#) (1)  
*A/R*
- [WIPS Calibration Software Test](#) (1)  
*Steps 11, 15, 17, and 24*
- [Micrometer](#) (1)  
*Steps 16 and 22*
- [Machinist's Scale](#) (2)  
*Accuracy of 1/16 inch or 1.5 mm, Step 21*
- [3/8" Drive Extension](#) (1)
- [Punch \(Center\)](#) (1)  
*3-Hole Type*
- [Sandpaper Sheets](#) (1)  
*Coarse*  
*Step 3*
- [Fabric Tape - Inches](#) (2)  
*Step 3*

### PARTS:

- [Spindle - Sold by Dozuki](#) (1)  
*Steps 1, 5, 11, 13, and 14*
- [Test Indicator](#) (1)  
*Steps 4, 5, 12, 13, and 14*
- [Magnetic Base](#) (1)  
*Steps 4 and 5*
- [Calibration Bar](#) (1)  
*Steps 4, 11, 16, 17, 20 and 21*
- [Ring Gauge - US](#) (1)
- [Work Probe](#) (5)  
*Steps 3, 5, and 21*
- [Punch-Down Tools](#) (1)
- [Wire Cutters](#) (1)
- [Rivet Gun MP-4V](#) (1)
- [FMMT495TA](#) (1.23)  
*Step 2*

## Step 1 — Verify Probe is Functioning Properly



- Check that the probe system and connections to the equipment are each functioning correctly.
  - Parts Required for this Step: **12133, 13131, 43121, 48382, 28392, 28210.**
    - ⚠ **Reminder:** Make sure to remove the **spindle** before starting the process.
  - Prior to beginning this procedure check to see if the fuse is dead. If the fuse is dead [go here](#).
    - Note:* View the [Ring Gauge](#) item page for more detailed part information.
  - Refer to the [Wiring Diagram](#) prior to starting step 4.

## Step 2



- In MDI, enter: **M59 P1134**.
- Hold the Work Probe within range of the **OMI**. Press and Hold **CYCLE START**.
- Gently depress the stylus, the control pendant will beep indicating the probe is activated.
- View [MSDS here](#)
- Contact Supervisor if there is a problem

### Step 3 — Calibration Tools:



- [Test Indicator](#) accurate to 0.0005" or 0.013 mm
  - [Magnetic Base](#) to mount the Indicator
  - [Calibration Bar](#) , generally consisting of a 1/2" or 12 mm gauge pin clamped in a collet style toolholder.
  - [Ring Gauge](#) typically with a 2.000" or 50.000 mm bore.
- ☒ **Note:** an accurately bored hole in a part or fixture can also be used in place of the Ring Gauge.


### Step 4



- Rotate the probe by hand to check runout.
- If runout exceeds 0.0005" or 0.013 mm, adjustment is required.
- Enter the runout reading.

## Step 5



 Please be aware of Quality Alert associated with the next step. [View Quality Alert.](#)


## Step 6

The screenshot shows the 'EDIT: IPS JOG' screen with the following data:


Parameter	Value
Z POSITION	-15.3321 in
X POSITION	-2.1656 in
Y POSITION	-3.3398 in
TOOL OFFSET	7
LENGTH	4.3800 in
DIAMETER	0.5005 in
CALIBRATION	INCOMPLETE

Additional interface elements include: 'MAIN SPINDLE' status (STOP, SPEED 0 RPM, SP LD: 0.0 KW, SURF SPD: 0 FPM, CHIP LOAD: 0.00000, FEED RATE: 0, ACT FEED: 0), 'POSITION: (IN)' (X: -2.1656, Y: -3.3398, Z: -15.3321), 'JOG RATE 0.0010', 'LOAD' (0%, 5%, 48%), 'ACTIVE TOOL MACHINE' (I7 - P8 I7, LOAD 0, LIFE 100%), and 'TOOL TYPE NOT SET'.

- Now enter the Spindle length. Use the value you wrote down in Step 1.
- Next, enter the runout reading previously noted in Step 4.


 **WARNING: THIS MUST BE A DIAMETER AND NOT A RADIUS MEASUREMENT.**

## Step 7



- This completes the calibration routine and the status box will display **COMPLETED**.
- With the Work Probe runout set within specification and both Probes calibrated, the machine is ready to measure tools and work pieces using the **WIPS** probing routines.
- Please complete [invalid guide link]

## Step 8 — Adjust stylus runout



- Insert the Work Probe into the spindle.
- Place the magnetic base on the table and align the indicator tip to the probe's stylus.
- Jog the axes in 0.001 inch increments until the indicator touches the stylus.
- With the indicator tip set against the stylus press **E-STOP**, so the probe isn't accidentally ejected during adjustment.

## Step 9 — Test Results



Record calibration test results.

## Data Capture

### Step 1

Serial Number

Verify probe and machine are working

Test Result (Choose one)

Pass

Fail

Measurement of Spindle (Choose one)

1/5"

1/4"

1/3"

1/2"

### Step 2



### Step 3

Verify required tools.

### Step 4

Runout Reading

### Step 5

I have read the Quality Alert.

### Step 6

Spindle Length

Runout Reading

### Step 9

Result (Choose one)

Pass

Fail

Observed Issues and Error Codes

This document was last generated on 2019-02-18 08:40:51 AM.