




make part nº2 (test)

smaller one side rounded part

Written By: jeanbaptiste




Step 1 — make part nº2 (test)



- rough cut rounded with plasma cutter or on torch table

Step 2



- 2 perforations 00" with drill press