

1. Introduction

Some tips for making the assembly easier.

Written By: Dozuki System



Step 1 — All the required tools are included




- ❗ No soldering is required.
- ❗ No wire crimping is required.

Step 2 — Use labels for reference



- ❗ Most of the labels are to scale 1:1 and can be used to identify the part :-)

Step 3 — Critical parts are spare back-uped



- Critical parts, like zipties, have a spare for back-up.
- No need to worry if you mess up wiring or something

Step 4 — View high resolution images



- ⓘ When you browse the guide on <http://manual.prusa3d.com>, you can view the original images in high resolution for clarity.
- Just hover your cursor over the image and click the "View Original" button.
- You can start by assembling Y-axis in the next chapter - [2. Y axis](#)